

Firmware 1.21.1 for Hasselblad H6D Multi-Shot

The 1.21.1 firmware is a service release for H6D Multi-Shot cameras that solves a reported bug.

Improvements compared to v1.21.0:

- Multi-Shot in 16-bit mode with Flash Delay = 0s now works as intended.

Update procedure

Make sure when initiating the update that the camera battery is charged with at least 50% power. Please note that the update procedure normally takes about 7-10 minutes, but can in some cases take up to 12 minutes.


IMPORTANT NOTES:

- Do not have the USB cable inserted during the update process.
- Wait until the message “Update Finished” appears. Then remove and reinsert the battery.


Copy the downloaded file (H6D_v1_21_1.cim) to the memory card and insert it into the camera. Then follow the procedure below:



1: Select the “General Settings Menu” from the main menu.



2: Select “Service”



3: Click “Check for Update” and select the file “H6D_v1_21_1.cim” from the list. Finally click “Update”.